Page 1 of 2

SAPC 12772

15 January 1957 COPY , 0F3

EXHIBIT A CHANGES TO SLOE FOR SYSTEMS 1 AND 3

Additions			NT 1			
MP Number	Nomenclature	Estimated Unit Cost	Number of Units	Estimated Amount		
10770	Test Jig for 02A with					
	Shield	\$ 99.89	1	\$ 99.89		
10767	Test Jig for 02B	142.76	1	142.76		
10751	Test Jig for 02C	146.24	1	146.24		
10776	Test Jig for 02D	144.08	1	144.08		
10749	Test Jig for 03	151.23	1	151.23		
10779	Test Jig for 04	170.97	1	170.97		
10553	Test Jig for 05	180.47	1	180.47		
10782	Test Jig for 03,04,					
	and 05	139.26	1	139.26		
10820	Test Probe R.F.	89.75	2	179.50		
10817	Cable Power	64.45	2	128.90		
10843	• - ** - ** - * - * - * - * - * - * - *					
	with MP 10767, MP 10					
	and MP 10776	15.75	1	15.75		
70026	Crystal Mount PRD					
	Type 613-M	56.00	2	112.00		
Deletions						
MP		•	Numbe:	r		
Number	Nomenclature			of Units		
	2 1 O211 O11 O1		OI OIII	OI OIIIts		
10209	Jig, Test for Elec	ctronics				
•	Board (System 3)	1				
QUANTITY CHANGES AND CORRECTIONS						
MP						
Number	Nomenclature		Instruc	Instruction		
						
10199	Test Set Ground f	Change	Change from MP 11007 and quantity from two			
		and qua				
	•		each to	one each.		
10506	Tripod, Test Horn (modified)		Change	Change estimated unit cost from \$12.50 each		
				95 each and		
				ed amount from		
			\$25.00	to \$59.90.		

MCC Doc. No. 1132X5.78

Approved For Release 2000/05/16 CIREP 81B008787001400040149-4

....

15 January 1957

EXHIBIT A COST SUMMARY CHANGES TO SLOE FOR SYSTEMS 1 AND 3

Additional Items:	
Material	\$ 1,545.95
General and Administrative Expense at 7.8%	 120.58
Estimated Cost Per List	\$ 1,665.53
ESTIMATED COST FOR THREE (3) LISTS	\$ 4,996.59
FIXED FEE AT 8,25%	 412.22
TOTAL ESTIMATED COST INCLUDING FEE	\$ 5,408.81